



## VOLVO V40: 1JUR212

Vinnumber:	<b>YV1MV8481F2232479</b>	Versionname:	<b>1.6 D2 SUMMUM</b>
First Registrationdate:	<b>2/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>95605</b>	Power Kw:	<b>84</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2211</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/50/17/93 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Dunlop: 7 mm</b>	Fr.R.	<b>Dunlop: 7 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>1155,12</b>
Alloy rim R L polished, Scratch(es), E - Replace			<b>235,20</b>



Ignition key, Missing, E - Replace 150,00

No pictures to display

Backrest cover F L, Worn, Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), E - Replace 235,20



Rearview mirror L complete, Scratch(es), Acceptable 0,00

No pictures to display

Floor covering F L, Burned, Smart repair 64,32



Centre console, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), E - Replace 235,20



Alloy rim F L polished, Scratch(es), E - Replace 235,20



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Seat cover R L, Scratch(es), Acceptable	0,00
---	------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Rocker panel inner F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display