



**VOLVO V70: 1JVK091**

Vinnumber:	<b>VV1BW8481F1330839</b>	Versionname:	
First Registrationdate:	<b>5/03/2015</b>	Fiscalpower:	<b>84</b>
Expertise Mileage:	<b>103617</b>	Power Kw:	<b>Beige</b>
Bodytype:	<b>Break</b>	Body color:	<b>Metalic</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Aluminium</b>
Transmission:	<b>Front</b>	Rims summer:	<b>OK</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3526</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	<b>No Tow bar</b>
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/96 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1512,05</b>
Bonnet, Hail damage, LI - Repair and paint (complete)	<b>348,09</b>



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Dent(s), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Roof pillar R, Dent(s), Acceptable

0,00

No pictures to display

Windscreen, Crack, E - Replace

560,64

