



BMW 3: 1HZY115

| | | | |
|-----------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber: | WBA3K11090F836413 | Versionname: | 3 TOURING 318d 136PK |
| First Registrationdate: | 12/11/2014 | Fiscalpower: | |
| Expertise Mileage: | 124373 | Power Kw: | 100 |
| Bodytype: | | Body color | BRUIN |
| Gearbox: | MAN 6 VIT | Body color | Dark Brown |
| Transmission: | Back | Paint type | Metalic |
| Fueltype: | Diesel | Rims summer | Aluminium |
| Maintenance | 24000 KM | Oil level | OK |
| Maintenance | OK | Parking lot | 2632 |
| Battery functioning | Yes | | |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| GPS storage | | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | Tow bar removable |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |
| Adaptive cruise control | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear



| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 205/60/16/92 H LightMetal | | | | |
| Winter tyres: | Fr.L. | Bridgestone: 7 mm | Fr.R. | Bridgestone: 7 mm |
| | Re.L. | Bridgestone: 7 mm | Re.R. | Bridgestone: 7 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--------------------------|---------------|
| Total cost ex VAT | 373,80 |
|--------------------------|---------------|

| | |
|--|-------------|
| Wing F R, Scratch(es), Acceptable | 0,00 |
|--|-------------|

| | | |
|---|--|--------|
| <i>No pictures to display</i> | | |
| Door F L, Dent(s), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Door R L, Dent(s), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Sill outer R, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Roof, Dent(s), PDR - Paintless dent repair | | 162,00 |
|  | | |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | | 211,80 |
|  | | |
| Door F R, Dent(s), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Bonnet, Dent(s), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |