


MITSUBISHI Outlander: 1EUU583

Vinnumber:	JMBXJGF6WDZ406019	Versionname:	OUTLANDER 2WD Xperience 150PK
First Registrationdate:	26/03/2013	Fiscalpower:	
Expertise Mileage:	147668	Power Kw:	110
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3512
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage		Seats electric F L	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/18/98 V LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			982,41
Door F R, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Bumper F, Scratch(es), LI - Repair and paint (complete)			254,16



Interior, Dirty, Acceptable 0,00

No pictures to display

Door F R, Bad repair, Paint 0,00



Bonnet, Chemical pollution, LI - Repair and paint (complete) 348,09



Internal Boot Lining R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bad repair, Paint 0,00



Bumper R, Dent(s), LI - Repair and paint (complete) 254,16



Door F L, Bad repair, Paint 0,00



Backrest cover F L, Scratch(es), Acceptable 0,00



Door R L, Bad repair, Paint 0,00



Wing R R, Bad repair, LI - Repair and paint (complete) 0,00



Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair	63,00
--	-------

