



MERCEDES B: 1JUP928

Vinnumber:	WDD2462121J312254	Versionname:	B 180CDI BE Edition 109PK
First Registrationdate:	2/03/2015	Fiscalpower:	
Expertise Mileage:	84129	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3613
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Kumho: 7 mm	Re.R.	Kumho: 7 mm

Assistance equipment

Repair kit	No	Compressor	No
------------	-----------	------------	-----------

Total cost ex VAT	1932,14
Door F R, Scratch(es), LI - Repair and paint (complete)	318,35



Wheel cover R L, Missing, E - Replace



Wheel cover F R, Missing, E - Replace 30,00



Door R R, Deformed / Strained, LI - Repair and paint (complete) 318,35



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (partial) 0,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Wheel cover R R, Scratch(es), E - Replace 30,00



Wheel cover F L, Not original part, E - Replace 30,00



Compressor, Missing, E - Replace 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Boot cover, Missing, E - Replace 50,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Scratch(es), It - Spot repair 115,56

