


OPEL Movano 3500 MWB Med.High Roof: 1GDH575

Vinnumber:	WOLMRFESCEB049643	Versionname:	MOVANO 3500 B/F L2H2 ecoFL.(E5)125PK
First Registrationdate:	7/01/2014	Fiscalpower:	
Expertise Mileage:	167220	Power Kw:	92
Bodytype:	Transporter	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV09
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	NOT OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/65/16/112 R Steel			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1514,22
Roof, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Broken, E - Replace	22,50



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 327,15




Seat cover F L, Worn, Acceptable 0,00



Sliding door R, Dent(s), LI - Repair and paint (complete) 382,02



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Air vent mid-dashboard, Broken, E - Replace 153,00



Bumper F, Scratch(es), E - Replace 398,40

