


**TOYOTA Grand Prius Plus: 1ESB684**

|                         |                   |              |                                       |
|-------------------------|-------------------|--------------|---------------------------------------|
| Vinnumber:              | JTDZS3EU303057175 | Versionname: | GRAND PRIUS+ Hybrid Comfort 99PK Aut. |
| First Registrationdate: | 6/03/2013         | Fiscalpower: |                                       |
| Expertise Mileage:      | 107603            | Power Kw:    | 73                                    |
| Bodytype:               | MPV               | Body color   | Silver                                |
| Gearbox:                | Automatic         | Paint type   | Metalic                               |
| Transmission:           |                   | Rims summer  | Steel                                 |
| Fueltype:               | Hybrid Petrol     | Oil level    | OK                                    |
| Battery functioning     | Yes               | Parking lot  | 3206                                  |
| Number of doors         | 5                 |              |                                       |
| Number of seats         | 7                 |              |                                       |
| Number head rests       | 7                 |              |                                       |
| Rims summer             | Steel             |              |                                       |
| Category                | Passenger Car     |              |                                       |
| Oil level               | OK                |              |                                       |

**Options**

|                                |                       |            |
|--------------------------------|-----------------------|------------|
| Radio CD                       | Panoramic roof        |            |
| Windows electric F             | Central consol F      |            |
| Windows electric R             | Luggage cover         |            |
| Cruise Control                 | Front parking sensors |            |
| Steering wheel multifunctional | Rear parking sensors  |            |
| Type of headlighting           | Type of Tow bar       | No Tow bar |
| Type of GPS                    | Headlighting Halogen  |            |
| Type of Lining                 | GPS big screen color  |            |
| Type of climate control        | Lining fabrics        |            |
| Head-up Display                | Autom climate control |            |

**Limited Technical Inspection**

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

**Degree of wear**

|               |                      |                |       |                |
|---------------|----------------------|----------------|-------|----------------|
| Winter tyres: | 205/60/16/92 H Steel |                |       |                |
|               | Fr.L.                | Michelin: 7 mm | Fr.R. | Michelin: 7 mm |
|               | Re.L.                | Michelin: 7 mm | Re.R. | Michelin: 7 mm |

**Assistance equipment**

|                                                         |         |
|---------------------------------------------------------|---------|
| Total cost ex VAT                                       | 1480,05 |
| Door F L, Scratch(es), LI - Repair and paint (complete) | 318,35  |



Wing F L, Dent(s), LI - Repair and paint (complete)

220,18



Foglight R, Broken, E - Replace

138,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Wheel cover R R, Missing, E - Replace

30,00



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Steel rim F R, Deformed / Strained, E - Replace

88,80



Wheel cover F R, Missing, E - Replace

30,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

