



VOLKSWAGEN PASSAT: 1KBB033

Vinnumber:	WVWZZZ3CZFE469778	Versionname:	1.6 TDI COMFORTLINE
First Registrationdate:	23/03/2015	Fiscalpower:	
Expertise Mileage:	136117	Power Kw:	88
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4823
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1294,13
Wing R L, Dent(s), PDR - Paintless dent repair	63,00



Bonnet prop, Missing, E - Replace

30,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

268,18



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bodywork, Not original part, Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Dent(s), LI - Repair and paint (complete)

414,35



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Rocker panel inner R L, Dent(s), Acceptable

0,00

No pictures to display