



BMW 5 TOURING: 1KXB843

Vinnumber:	WBA5L11020G322919	Versionname:	2.0 518D (100KW) TOURING
First Registrationdate:	20/07/2015	Fiscalpower:	
Expertise Mileage:	106346	Power Kw:	100
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2808
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 H LightMetal				
Winter tyres:	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Total cost ex VAT	3395,52
Rearview mirror housing R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R L, Chemical polution, LI - Repair and paint (complete) 369,84




Ignition key, Missing, E - Replace 150,00

No pictures to display

Rearview mirror housing L, Scratch(es), 67 - Polish 0,00

No pictures to display

Roof pillar R, Chemical polution, LI - Repair and paint (complete) 264,22



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16



Roof pillar L, Chemical polution, 67 - Polish 0,00

No pictures to display

Wing F L, Chemical polution, LI - Repair and paint (complete) 264,21



Protection plate M, Tear, E - Replace 74,00




Door R R, Chemical polution, LI - Repair and paint (complete) 382,02



Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09




Tailgate, Dent(s), LI - Repair and paint (complete)

362,02



Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16

