



VOLVO V40: 1KFC211

Vinnumber:	YV1MV8481F2248227	Versionname:	1.6 D2 KINETIC
First Registrationdate:	20/04/2015	Fiscalpower:	
Expertise Mileage:	113345	Power Kw:	84
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	8 MAAND	Parking lot:	4333
Maintenance:	10230		
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			401,09
Alloy rim F R, Scratch(es), Acceptable			0,00

Door R R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Tyre repair kit, Missing, E - Replace	210,53



Wing R L, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), It - Spot repair	115,56



Wing F R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Compressor, Missing, E - Replace	75,00



Door F R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	