


VOLKSWAGEN Polo: 1DLV478

| | | | |
|-------------------------|--------------------------|--------------|----------------------------------|
| Vinnumber: | WVWZZZ6RZDY006502 | Versionname: | POLO Comfortline DPF 75PK |
| First Registrationdate: | 19/06/2012 | Fiscalpower: | |
| Expertise Mileage: | 130235 | Power Kw: | 55 |
| Bodytype: | Hatchback | Body color: | White |
| Gearbox: | MAN 5 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4533 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | | |
|-------------------------|------------------------------|-----------------|-------------------|
| Radio CD | | Luggage cover | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Windows electric R | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | No GPS | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 185/60/15/84 H Steel | | | |
| Summer tyres: | Fr.L. | Hankook: 5 mm | Fr.R. | Hankook: 5 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

Total cost ex VAT

795,56

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56


Wheel cover R R, Scratch(es), Acceptable

0,00

| | | |
|---|--|--------|
| <i>No pictures to display</i> | | |
| Bonnet, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Bumper R, Broken, LI - Repair and paint (complete) | | 169,44 |
| | | |
| Wheel cover R L, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Roof, Dent(s), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Bumper F, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Wheel cover F R, Scratch(es), E - Replace | | 24,00 |
| | | |
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | | 246,56 |
| | | |
| Door F L, Bad repair, Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Wing R L, Dent(s), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Floor covering F L, Hole, E - Replace | | 240,00 |

