



VOLVO XC60: 1FAN369

Vinnumber:	VV1DZ31A1D2464021	Versionname:	XC60 D3 Kinetic Start/Stop 136PK
First Registrationdate:	7/05/2013	Fiscalpower:	
Expertise Mileage:	140416	Power Kw:	100
Bodytype:	SUV	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1425
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/17/108 H LightMetal				
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	820,82
Wing F R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper R, Scratch(es), Smart repair 110,64



Bonnet, Chemical polution, Acceptable 0,00

No pictures to display

Protection plate M, Hole, E - Replace 74,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Windscreen, Stone chip(s), Acceptable 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



