



**LU Audi a3 Sportback: GD4289**

|                                    |                         |              |   |
|------------------------------------|-------------------------|--------------|---|
| Vinnumber:                         | <b>WAUZZZ8VXF145094</b> | Versionname: | <b>2.0 TDI 110KW CLEAN DIESEL AMBIENTE SB</b> |
| First Registrationdate:            | <b>3/04/2015</b>        | Fiscalpower: |   |
| Expertise Mileage:                 | <b>128639</b>           | Power Kw:    | <b>110</b>                                    |
| Bodytype:                          |                         | Body color:  | <b>Grey</b>                                   |
| Gearbox:                           | <b>MAN 6 VIT</b>        | Paint type:  | <b>Metalic</b>                                |
| Transmission:                      | <b>Front</b>            | Rims summer: | <b>Aluminium</b>                              |
| Fueltype:                          | <b>Diesel</b>           | Oil level:   | <b>OK</b>                                     |
| Battery functioning:               | <b>Yes</b>              | Parking lot: | <b>4206</b>                                   |
| Number of doors:                   | <b>5</b>                |              |   |
| Number of seats:                   | <b>5</b>                |              |   |
| Number head rests:                 | <b>5</b>                |              |   |
| Rims summer:                       | <b>Aluminium</b>        |              |   |
| Category:                          | <b>Passenger Car</b>    |              |   |
| Oil level:                         | <b>OK</b>               |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>              |              |   |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional | Type of Tow bar              |
| Radio multimedia               | <b>No Tow bar</b>            |
| Type of headlighting           | <b>Headlighting Xenon</b>    |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining semi-leather</b>   |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>205/55/16/91 H LightMetal</b> |       |                          |       |                          |
| Winter tyres:                    | Fr.L. | <b>Continental: 4 mm</b> | Fr.R. | <b>Continental: 4 mm</b> |
|                                  | Re.L. | <b>Continental: 4 mm</b> | Re.R. | <b>Continental: 4 mm</b> |

**Assistance equipment**

|  |            |      |            |
|--|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|  |               |
|--|---------------|
| <b>Total cost ex VAT</b>                                       | <b>789,30</b> |
| <b>Bumper F, Scratch(es), LI - Repair and paint (complete)</b> | <b>211,80</b> |



|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                             |      |
|-----------------------------|------|
| Bonnet, Dent(s), Acceptable | 0,00 |
|-----------------------------|------|

No pictures to display

|  |      |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

|   |        |
|---|--------|
| Roof, Chemical polution, LI - Repair and paint (complete) | 577,50 |
|---|--------|

