



VOLKSWAGEN TOURAN: 1KHJ965

Vinnumber:	WVGZZZ1TZFW081318	Versionname:	1.6 CR TDI TRENDLINE BLUEMOTION TECH
First Registrationdate:	5/05/2015	Fiscalpower:	
Expertise Mileage:	74039	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3633
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1554,30
Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R R polished, Scratch(es), LI - Repair and paint (complete) 95,00





Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Bad repair, Acceptable

0,00



Alloy rim R R polished, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Luggage space cover, Worn, Smart repair

110,64



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R L polished, Scratch(es), Acceptable

0,00

No pictures to display