


BMW 518: 1HNV628

Vinnumber:	WBA5J11080D336170	Versionname:	TOURING 518d 136PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	169221	Power Kw:	100
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1513
Maintenance:	OVER 2800 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/101 W LightMetal				
Summer tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	No
Total cost ex VAT			1545,52
Windscreen, Stone chip(s), E - Replace			560,64



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Dent(s), Acceptable 0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 350,16



Door frame R L, Dent(s), It - Spot repair 115,56



Compressor, Missing, E - Replace 75,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable 0,00



Door panel F L, Worn, Acceptable 0,00



Maintenance, Maintenance, P - Check 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Door F L, Scratch(es), Acceptable

0,00

