


BMW 518 TOURING: 1JEY637

Vinnumber:	WBA5L11020D785855	Versionname:	5 TOURING 518da 136PK Aut.
First Registrationdate:	28/11/2014	Fiscalpower:	
Expertise Mileage:	182653	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2212
Maintenance:	08-2020 OU 1.400 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/101 W LightMetal			
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	724,32
-------------------	--------

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	350,16
---	--------




Wing R L, Dent(s), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Boot carpet, Chemical polution, E - Replace	120,00
--	---------------



Door F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
--	---------------



Alloy rim R R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display