



LEXUS IS: 1GUL998

Vinnumber:	JTHBH5D2205027048	Versionname:	IS 300h BER Business Ed.E-CVT 177PK Aut.
First Registrationdate:	5/05/2014	Fiscalpower:	
Expertise Mileage:	113127	Power Kw:	133
Bodytype:	Berline	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1408
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT		2674,48
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)		211,80



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Wing F R, Scratch(es), Acceptable


0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80





Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56




Bumper cover R M, Dent(s) and scratch(es), Smart repair

110,64



Roof, Scratch(es), LI - Repair and paint (complete)

481,50





Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08



Door F R, Bad repair, Acceptable 0,00

