



AUDI A6: 1JAL818

Vinnumber:	WAUZZZ4G0EN195923	Versionname:	A6 AVANT Ultra S-tr. 190PK Aut.
First Registrationdate:	18/11/2014	Fiscalpower:	
Expertise Mileage:	133699	Power Kw:	140
Bodytype:	Break	Body color:	Red
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1315
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/60/16/98 H LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 2 mm	Fr.R.	Uniroyal: 2 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 2993,49

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Tyre repair kit, Missing, E - Replace 252,64



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56




Door F R, Scratch(es), Acceptable 0,00

No pictures to display
Roof, Chemical polution, Acceptable 0,00

No pictures to display
Door R R, Scratch(es), Acceptable 0,00

No pictures to display
Tailgate, Scratch(es), Acceptable 0,00

No pictures to display
Rear window, Scratch(es), E - Replace 420,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display
Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 25,00

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Interior, Dirty, Chemical cleaning

25,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
---	--------

