


PEUGEOT 308: 1GUH311

Vinnumber:	VF3LB9HPAES092449	Versionname:	308 BER Active 92PK
First Registrationdate:	2/05/2014	Fiscalpower:	
Expertise Mileage:	131135	Power Kw:	68
Bodytype:	Hatchback	Body color:	Purple
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3230
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	4059,93
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Burned, E - Replace	252,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door panel R L, Scratch(es), Smart repair

110,64



Inner door handle F L, Scratch(es), E - Replace

36,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Foglight R, Broken, E - Replace

138,00



Trunk lid covering R, Scratch(es), Smart repair

110,64



Rocker panel inner F L, Dent(s), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Roof, Chemical pollution, LI - Repair and paint (complete) 529,50



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50





Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Rocker panel inner R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Rocker panel inner R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Broken, Le - Replace and paint

735,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Roof pillar R, Dent(s), Acceptable 0,00

No pictures to display