



BMW 4 Gran Coupe: 1JGP507

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber: | WBA4D51040D424496 | Versionname: | 4 GRAN COUPE 418d 136PK |
| First Registrationdate: | 12/12/2014 | Fiscalpower: | |
| Expertise Mileage: | 138706 | Power Kw: | 100 |
| Bodytype: | Berline | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4315 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 4 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Sun Roof electric | |
| GPS storage | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |
| Head-up Display | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|----------------------|-------|----------------------|
| 225/50/17/94 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Hankook: 4 mm | Fr.R. | Hankook: 4 mm |
| | Re.L. | Hankook: 4 mm | Re.R. | Hankook: 4 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--|----------------|
| Total cost ex VAT | 1448,14 |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 254,16 |



| | |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Bad repair, Acceptable | 0,00 |



| | |
|----------------------------------|------|
| Door R L, Bad repair, Acceptable | 0,00 |
|----------------------------------|------|



| | |
|---|--------|
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 254,16 |
|---|--------|



| | |
|---|--------|
| Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) | 362,02 |
|---|--------|



| | |
|---|--------|
| Roof, Chemical polution, LI - Repair and paint (complete) | 577,80 |
|---|--------|



Door F L, Scratch(es), Acceptable

0,00

No pictures to display