



VOLVO S60: 1EMA920

Vinnumber:	YV1F584ABD2211313	Versionname:	S60 BER D2 Kinetic St/St Pow.115PK Aut.
First Registrationdate:	18/01/2013	Fiscalpower:	
Expertise Mileage:	102406	Power Kw:	84
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2506
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 0 mm	Re.R.	Michelin: 0 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 2455,05

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20





Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00




Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Tyre R R, Worn, E - Replace

132,00




Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Deformed / Strained, LI - Repair and paint (complete)

211,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Foglight L, Broken, E - Replace

138,00

