


MERCEDES B: 1HTU596

Vinnumber:	WDD2462121J289289	Versionname:	B 180CDI BE Edition 109PK
First Registrationdate:	1/10/2014	Fiscalpower:	
Expertise Mileage:	193133	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2709
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	490,00
-------------------	---------------

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door R L, Repaired, Acceptable	0,00
--------------------------------	-------------

No pictures to display

Alloy rim F R, Scratch(es), L L, Dent and paint (complete)	0,00
--	-------------

Alloy rim F R, Scratch(es), LI - repair and paint (complete)

95,00



Engine, Not functioning (well), P - Check

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door frame R R, Dent(s), Acceptable

0,00

No pictures to display

Roof, Chemical pollution, Acceptable

0,00

No pictures to display

Wing F R, Bad repair, Acceptable

0,00



Ignition key, Missing, E - Replace

150,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar R, Repaired, Acceptable

0,00

No pictures to display

Certificate Of Conformity, Missing, E - Replace

150,00

No pictures to display

Wing R L, Bad repair, Acceptable

0,00



Door R R, Bad repair, Acceptable

0,00

