



BMW X5: 1HCG148

Vinnumber:	WBAKS410900H48979	Versionname:	X5 3.0dA xDrive30 258PK Aut.
First Registrationdate:	17/06/2014	Fiscalpower:	
Expertise Mileage:	138626	Power Kw:	190
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3625
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

255/50/19/107 H LightMetal				
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	1906,11
-------------------	----------------

Protection plate M, Tear, E - Replace	124,00
---------------------------------------	---------------



Wing moulding F R, Scratch(es), E - Replace

31,68



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00




Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16




Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door panel R R, Tear, E - Replace

132,00



Interior, Dirty, Acceptable

0,00

No pictures to display



Interior, Dirty, Acceptable

0,00

No pictures to display

Door panel R R, Tear, E - Replace

132,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Ignition key, Not functioning (well), Acceptable

0,00



Spoiler R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display


Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display