



AUDI A5: 1ECZ010			
Vinnumber:	WAUZZZ8T1DA032971	Versionname:	A5 SB TDie DPF 136PK
First Registrationdate:	24/10/2012	Fiscalpower:	
Expertise Mileage:	201480	Power Kw:	100
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2729
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment	
Emergency spare wheel	Yes

Total cost ex VAT	4369,81
Windscreen, Scratch(es), E - Replace	560,64



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Full screen GPS, Not functioning (well), P - Check

0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00




Tailgate, Scratch(es), LI - Repair and paint (complete)

362,02



Bonnet, Chemical pollution, LI - Repair and paint (complete)

348,09



Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21



Trunk lid covering R, Broken, Smart repair

110,64



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete)

382,02



Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Wing F L, Chemical polution, LI - Repair and paint (complete)

264,21



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bagage rack, Deformed / Strained, Repair/replace (lump sum) 50,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display