



RENAULT KANGOO EXPRESS: 1KFP235

Vinnumber:	VF1FW18H552901456	Versionname:	1.5DCI 90 MAXI GRAND CONFORT
First Registrationdate:	22/04/2015	Fiscalpower:	
Expertise Mileage:	128974	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV20
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Type of Tow bar	Tow bar fixed
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 T Steel			
Summer tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	895,35
-------------------	---------------

Rearview mirror L complete, Broken, E - Replace	138,00
---	---------------



Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Wheel cover F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

no pictures to display

Trunk door R L, Dent(s) and scratch(es), It - Spot repair 115,56



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Hole, E - Replace 300,00



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Repaired, Acceptable 0,00

No pictures to display

Bumper F, Dent(s), Smart repair 110,64

