



BMW 3 GT: 1DKQ805

Vinnumber:	WBA3Y11020D448479	Versionname:	
First Registrationdate:	16/01/2014	Fiscalpower:	100
Expertise Mileage:	102274	Power Kw:	Grey
Bodytype:	Hatchback	Body color:	Metalic
Gearbox:	MAN 6 VIT	Paint type:	Aluminium
Transmission:	Back	Rims summer:	OK
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	VABFS BMB
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/18/95 W LightMetal				
Summer tyres:	Fr.L.	Pirelli: 6,5 mm	Fr.R.	Pirelli: 6,5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	1483,15
Windscreen, Stone chip(s), Windscreen repair	58,80



Door F L, Repaired, Acceptable 0,00

No pictures to display

Rocker panel inner F L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door panel R L, Tear, E - Replace 114,00



Door R R, Dent(s), LI - Repair and paint (complete) 366,35



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer L, Scratch(es), It - Spot repair 115,56



Wing F L, Bad repair, LI - Repair and paint (complete) 0,00



Roof pillar R, Dent(s), PDR - Paintless dent repair

63,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Outer backrest protection R, Scratch(es), Smart repair

110,64



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar L, Dent(s), PDR - Paintless dent repair

63,00



Door panel R R, Scratch(es), Acceptable

0,00

No pictures to display