



SEAT ALHAMBRA: 1NGN652

Vinnumber:	VSSZZZ7N2GV717021	Versionname:	2.0 TDI 110KW STYLE ECOMOTIVE
First Registrationdate:	19/02/2016	Fiscalpower:	
Expertise Mileage:	112028	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3603
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 H LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	3487,44
Luggage space cover, Damaged, Smart repair	110,64




Sidewall panel RL, Broken, E - Replace

20,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02




Wing F R, Bad repair, Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace


560,64



Tailgate, Bad repair, Acceptable

0,00





Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Trunk lid covering R, Scratch(es), Smart repair

110,64





Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Rearlight R , Scratch(es), 67 - Polish

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Bad repair, Acceptable

0,00



Boot carpet, Damaged, Smart repair

64,32



Internal Boot Lining L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84

Wing R L, Scratch(es), LI - Repair and paint (complete)

389,02



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

430,02




Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Internal Boot Lining R, Scratch(es), Acceptable

0,00

No pictures to display