



**LU Skoda Octavia Combi: SF8399**

|                                    |                          |              |                                     |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnumber:                         | <b>TMBJJ9NE1F0226468</b> | Versionname: | <b>2.0 TDI 110KW ELEGANCE COMBI</b> |
| First Registrationdate:            | <b>7/05/2015</b>         | Fiscalpower: |                                     |
| Expertise Mileage:                 | <b>138584</b>            | Power Kw:    | <b>110</b>                          |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>White</b>                        |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                      |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                    |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                           |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4231</b>                         |
| Number of doors:                   | <b>5</b>                 |              |                                     |
| Number of seats:                   | <b>5</b>                 |              |                                     |
| Number head rests:                 | <b>5</b>                 |              |                                     |
| Rims summer:                       | <b>Aluminium</b>         |              |                                     |
| Category:                          | <b>Passenger Car</b>     |              |                                     |
| Oil level:                         | <b>OK</b>                |              |                                     |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                     |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Central consol F      |                   |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |                   |
| GPS storage                    |                              | Front parking sensors |                   |
| Windows electric F             |                              | Rear parking sensors  |                   |
| Windows electric R             |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Cruise Control                 |                              |                       |                   |
| Steering wheel multifunctional |                              |                       |                   |
| Seats F heated                 |                              |                       |                   |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |
| Adaptive cruise control        |                              |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>205/55/16/91 H LightMetal</b> |       |                          |       |                          |
| Winter tyres:                    | Fr.L. | <b>Continental: 4 mm</b> | Fr.R. | <b>Continental: 4 mm</b> |
|                                  | Re.L. | <b>Continental: 5 mm</b> | Re.R. | <b>Continental: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>424,20</b> |
|-------------------|---------------|

|                             |             |
|-----------------------------|-------------|
| Bonnet, Dent(s), Acceptable | <b>0,00</b> |
|-----------------------------|-------------|

No pictures to display

|                           |             |
|---------------------------|-------------|
| Roof, Dent(s), Acceptable | <b>0,00</b> |
|---------------------------|-------------|

No pictures to display


Interior, Dirty, Cleaning

75,00




Trunk lid covering R, Scratch(es), E - Replace

74,40



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

