



BMW 3: HA9585

Vinnumber:	WBA3J31050F813788	Versionname:	3 BER 318dX 143PK
First Registrationdate:	8/12/2014	Fiscalpower:	
Expertise Mileage:	172579	Power Kw:	105
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1410
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 Y LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

	Runflat	Yes
--	---------	------------

Total cost ex VAT	587,60
-------------------	---------------

Seat cover F L, Damaged, Acceptable	0,00
-------------------------------------	-------------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Door panel R R, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Dent(s), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Dent(s), PDR - Paintless dent repair	63,00



Alloy rim R R, Scratch(es), Acceptable	0,00
No pictures to display	
Instrument panel cover, Scratch(es), E - Replace	89,00



Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Seat cover R L, Incomplete, E - Replace	12,00



Door F L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80





Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display