



MERCEDES CLA: 1HSC087

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnumber: | WDD1173121N139906 | Versionname: | CLA BER 180 CDI 109PK |
| First Registrationdate: | 18/09/2014 | Fiscalpower: | |
| Expertise Mileage: | 110657 | Power Kw: | 80 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2223 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|-------------------------|-------------------------------|
| Radio CD | Panoramic roof |
| Windows electric F | Central consol F |
| Windows electric R | Type of Tow bar |
| Radio multimedia | No Tow bar |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining semi-leather |
| Type of climate control | Manual climate control |
| Sport seats | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 225/40/18/92 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 8 mm | Fr.R. | Continental: 8 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|------------|-----------|------------|------------|
| Repair kit | No | Compressor | Yes |
|------------|-----------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 730,73 |
|-------------------|---------------|

| | |
|--|---------------|
| Alloy rim F R polished, Scratch(es), E - Replace | 235,20 |
|--|---------------|





| | |
|---|-------|
| Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|---|-------|



| | |
|---------------------------------------|--------|
| Tyre repair kit, Missing, E - Replace | 210,53 |
|---------------------------------------|--------|

No pictures to display

| | |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|-------|
| Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|---|-------|



| | |
|----------------------------------|------|
| Bumper R, Bad repair, Acceptable | 0,00 |
|----------------------------------|------|



| | |
|---|-------|
| Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|---|-------|

