



VOLVO V60: 1KSA313

Vinnumber:	YV1FWA8C1G1291560	Versionname:	2.0 D4 KINETIC
First Registrationdate:	19/06/2015	Fiscalpower:	
Expertise Mileage:	141816	Power Kw:	140
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1315
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/97 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	No	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2101,68
Rocker panel inner R L, Dent(s), Acceptable	0,00



Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20



Sill outer L, Scratch(es), LI - Repair and paint (complete)	310,50
---	--------



Sill outer R, Scratch(es), LI - Repair and paint (complete)	310,50
---	--------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>	
-------------------------------	--

Interior, Dirty, Cleaning	0,00
---------------------------	------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>	
-------------------------------	--

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>	
-------------------------------	--

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper Trim F, Missing, E - Replace

30,00



Tyre repair kit, Missing, E - Replace

210,53



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35

