



**BMW 3 TOURING: 1KAY226**

Vinnumber:	<b>WBA3K11040F838957</b>	Versionname:	<b>2.0 318D (100KW) TOURING</b>
First Registrationdate:	<b>23/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>91830</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1508</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>












**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Total cost ex VAT	2107,20
Windscreen, Stone chip(s), E - Replace	487,20



<i>No pictures to display</i>		
Wing R L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), I - Repair		100,00
		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Foglight R, Crack, E - Replace		138,00
		
Wing F L, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Parking sensor R, Not functioning (well), Forfeit		25,00
		
Floor covering F L, Tear, E - Replace		252,00
		
Bumper F, Crack, Le - Replace and paint		735,00
		
Bumper R, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Rear window, Scratch(es), E - Replace		370,00
