


OPEL COMBO: 1PFL524

Vinnumber:	W0L6ZYC1AH9596112	Versionname:	1.3 CDTI 66KW 2.0T SWB
First Registrationdate:	23/06/2016	Fiscalpower:	
Expertise Mileage:	56189	Power Kw:	66
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV05
Number of doors:	4		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Type of Tow bar	No Tow bar
Windows electric F			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T Steel			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1358,66
Roof, Chemical polution, Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Smart repair	110,64



Bodywork, Not original part, Acceptable 0,00

No pictures to display
 Bumper R, Dent(s) and scratch(es), E - Replace 329,40



Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Bonnet, Chemical polution, LI - Repair and paint (complete) 217,56



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display