


OPEL ASTRA SPORTS TOURER: 1JGP503

Vinnumber:	WOLPD8E69F8024353	Versionname:	1.6 CDTI 81KW ECOFLEX S/S BUSINESS
First Registrationdate:	12/12/2014	Fiscalpower:	
Expertise Mileage:	137065	Power Kw:	81
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2407
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2157,11
--------------------------	----------------

Wing R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Rear spoiler, Chemical polution, LI - Repair and paint (complete)

115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Floor covering F L, Hole, E - Replace

252,00





Roof pillar R, Chemical polution, LI - Repair and paint (complete) 220,18



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s), LI - Repair and paint (complete) 220,18



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80





Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

