



OPEL COMBO: 1PFL547

Vinnumber:	W0L6ZYC1AH9596236	Versionname:	1.3 CDTI 66KW 2.0T SWB
First Registrationdate:	23/06/2016	Fiscalpower:	
Expertise Mileage:	49379	Power Kw:	66
Bodytype:	Transporter	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV29
Number of doors:	4		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Type of Tow bar	No Tow bar
Windows electric F		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1628,73
Door F L, Chemical polution, Acceptable	0,00
No pictures to display	
Trunk door R R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Wing F L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Dent(s), LI - Repair and paint (complete)	303,15



Bumper F, Scratch(es), Smart repair

110,64



Tailgate, Scratch(es), LI - Repair and paint (complete)

362,02



Bodywork, Not original part, Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00

No pictures to display


Bumper R, Scratch(es), Smart repair

110,64



Roof, Chemical polution, LI - Repair and paint (complete)

361,13



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), LI - Repair and paint (complete) 231,15

