



OPEL Movano 3500 MWB Med.High Roof: 1GNJ707

Vinnumber:	WOLMRFESCEB049227	Versionname:	MOVANO 3500 B/F L2H2 ecoFL.(E5)125PK
First Registrationdate:	18/03/2014	Fiscalpower:	
Expertise Mileage:	202021	Power Kw:	92
Bodytype:	Transporter	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV08
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	225/65/16/112 R Steel			
	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 9 mm	Re.R.	Uniroyal: 9 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	1579,02
-------------------	----------------

Wing trim R R, Scratch(es), E - Replace	69,00
---	--------------



Door moulding Lower F R, Scratch(es), E - Replace	91,50
---	--------------



Seat cover F L, Damaged, E - Replace

300,00



Rearview mirror R complete, Broken, E - Replace

138,00




Wing trim R R, Scratch(es), E - Replace

69,00



Door R R, Dent(s), LI - Repair and paint (complete)

238,76




Door R L, Dent(s), Acceptable

0,00

No pictures to display

Windscreen, Crack, E - Replace

0,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 232,88



Door moulding Lower R R, Scratch(es), E - Replace 91,50



Foglight L, Missing, E - Replace 115,50

