



VOLKSWAGEN Crafter 35 MWB: 1ALZ512

Vinnumber:	WV1ZZZ2FZB7004587	Versionname:	CRAFTER 35 LB2C MWB 109PK
First Registrationdate:	7/02/2011	Fiscalpower:	
Expertise Mileage:	244591	Power Kw:	80
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV03
Number of doors:	4		
Number of seats:	7		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Type of Tow bar	No Tow bar
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining artificial leather		
Type of climate control	No climate control		

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/16/115 R Steel				
Summer tyres:	Fr.L.	Michelin: 8 mm	Fr.R.	Michelin: 8 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	1616,04
-------------------	---------

Seat cover F R, Tear, E - Replace	300,00
-----------------------------------	--------



Door R R, Rust, LI - Repair and paint (complete)	238,76
--	--------



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Rearview mirror glass R, Broken, E - Replace 13,50



Sill outer L, Rust, LI - Repair and paint (complete) 232,88



Bumper F, Scratch(es), Smart repair 110,64



Seat cover F L, Tear, E - Replace 300,00



Headrest F L, Missing, E - Replace 45,00



Rearlight R, Broken, E - Replace 91,50



Headrest R M, Missing, E - Replace 45,00



Door R L, Rust, LI - Repair and paint (complete) 238,76





Bumper F, Dent(s), Acceptable 0,00

No pictures to display

Steering wheel, Worn, Acceptable 0,00

