



VOLVO V60: 1JVB730

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------|
| Vinnumber: | YV1FW8481F1260482 | Versionname: | 1.6 D2 KINETIC |
| First Registrationdate: | 4/03/2015 | Fiscalpower: | |
| Expertise Mileage: | 150767 | Power Kw: | 84 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OVER 6909KM | Parking lot: | 3404 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| GPS storage | | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-------------------------|-------|-------------------------|
| 205/60/16/96 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Vredestein: 5 mm | Fr.R. | Vredestein: 5 mm |
| | Re.L. | Vredestein: 6 mm | Re.R. | Vredestein: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

Total cost ex VAT 534,97

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Protection plate M, Deformed / Strained, Acceptable 0,00



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Door R L, Dent(s) and scratch(es), It - Spot repair 115,56



Door frame R R, Scratch(es), Acceptable 0,00

No pictures to display

Covering interior A pillar L, Burned, E - Replace 38,85



Door R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), It - Spot repair 115,56





Door frame R L, Dent(s), Acceptable 0,00

No pictures to display

Interior, Stain, Shampooing 75,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Outer door handle R R, Scratch(es), Acceptable 0,00

No pictures to display