



**TOYOTA Auris: 1GXJ637**

Vinnumber:	<b>SB1ZS3JE20E096105</b>	Versionname:	<b>AURIS TOUR.SP. HSD Lounge CVT 99PK Aut.</b>
First Registrationdate:	<b>27/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>66632</b>	Power Kw:	<b>73</b>
Bodytype:	<b>Break</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1526</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/45/17/91 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Dunlop: 6 mm</b>	Fr.R.	<b>Dunlop: 6 mm</b>
	Re.L.	<b>Dunlop: 3 mm</b>	Re.R.	<b>Dunlop: 3 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 4434,15

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover R R, Unclasp(ed), Repair/replace (lump sum)

48,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Sill trim R R, Broken, Repair/replace (lump sum)

48,00



Wing F L, Dent(s), LI - Repair and paint (complete)

220,18



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Bumper grille, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), E - Replace

370,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Sill outer L, Dent(s), LI - Repair and paint (complete)

310,50



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Tyre repair kit, Missing, E - Replace

210,53



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Spoiler R, Dent(s) and scratch(es), It - Spot repair

115,56



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Sill outer R, Dent(s), LI - Repair and paint (complete)

310,50



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Tyre R L, Tear, E - Replace


132,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Windscreen, Scratch(es), E - Replace 487,20



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80





Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Chemical pollution, LI - Repair and paint (complete)

290,08