



**VOLKSWAGEN Crafter 35 MWB: 1BJR421**

Vinnumber:	<b>WV1ZZZ2FZB7005553</b>	Versionname:	<b>CRAFTER 35 LB2C MWB 109PK</b>
First Registrationdate:	<b>16/06/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>193763</b>	Power Kw:	<b>80</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV04</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>No climate control</b>		

**Limited Technical Inspection**

Tires wear profile	<b>OK</b>	Battery functioning	<b>Yes</b>
Idle position	<b>OK</b>	Power steering	<b>Yes</b>
Engine startingtime	<b>OK</b>	Sound engine	<b>OK</b>
Exhaust gass	<b>OK</b>	Clutch test	<b>OK</b>
Handbrake	<b>OK</b>	Wiper fluid level	<b>OK</b>
		Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/65/16/119 R Steel</b>				
Summer tyres:	Fr.L.	<b>Michelin: 7 mm</b>	Fr.R.	<b>Michelin: 7 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	<b>2649,24</b>
Door R L, Scratch(es), LI - Repair and paint (complete)	<b>238,76</b>





Windscreen, Crack, E - Replace

395,40



Seat cover F L, Hole, E - Replace

300,00



Bumper F L, Dent(s) and scratch(es), It - Spot repair

115,56



Door F R, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

Sidewall RR (LCV), Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

A-pillar right, Dent(s) and scratch(es), LI - Repair and paint (complete)

124,23



Sidewall RL (LCV), Scratch(es), Acceptable

0,00

*No pictures to display*

Boot carpet, Hole, E - Replace

196,00





Rocker panel inner F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 165,13



Seat cover F R, Worn, Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Hole, E - Replace 91,50



Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), Le - Replace and paint 385,50



Bumper F, Deformed / Strained, E - Replace 398,40



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76





Dashboard, Hole, Acceptable

0,00

