



SKODA OCTAVIA COMBI: 1LUU042

Vinnumber:	TMBJB9NE6G0138403	Versionname:	1.2 TSI 81KW DSG 7 GREENTEC STYLE
First Registrationdate:	10/12/2015	Fiscalpower:	
Expertise Mileage:	150668	Power Kw:	81
Bodytype:	Break	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2522
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/94 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 0,00

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 0,00



Trunk lid covering R, Scratch(es), Smart repair

0,00



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Repaired, Acceptable

0,00



Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete)

0,00



Sidewall panel RL, Missing, E - Replace

0,00



Door R R, Scratch(es), LI - Repair and paint (complete)

0,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Protection plate M, Missing, E - Replace 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 0,00




Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 0,00





Roof, Chemical polution, LI - Repair and paint (complete)

0,00



Internal Boot Lining L, Hole, Smart repair

0,00

