



VOLKSWAGEN SHARAN: 1KAN897

Vinnumber:	WVWZZZ7NZFV031664	Versionname:	2.0 CR TDI 100KW HIGHLINE BMT
First Registrationdate:	19/03/2015	Fiscalpower:	
Expertise Mileage:	117197	Power Kw:	100
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1732
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

225/50/17/98 V LightMetal				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	4473,98
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Air vent R M, Broken, E - Replace

158,40



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Rear spoiler, Chemical polution, LI - Repair and paint (complete)

115,56



Cupholder R, Broken, E - Replace

44,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84




Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16





Wing F R, Dent(s), LI - Repair and paint (complete) 264,21



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Luggage space cover, Missing, E - Replace 288,00

No pictures to display

Boot carpet, Dirty, Cleaning 50,00



Door R R, Scratch(es), LI - Repair and paint (complete)

382,02

