



**AUDI A3: 1FPQ751**

|                                    |                          |              |                             |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber:                         | <b>WAUZZZ8V6EA051440</b> | Versionname: | <b>A3 SB Ambiente 105PK</b> |
| First Registrationdate:            | <b>17/09/2013</b>        | Fiscalpower: |                             |
| Expertise Mileage:                 | <b>151362</b>            | Power Kw:    | <b>77</b>                   |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Black</b>                |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>              |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>            |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                   |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>TRU10</b>                |
| Number of doors:                   | <b>5</b>                 |              |                             |
| Number of seats:                   | <b>5</b>                 |              |                             |
| Number head rests:                 | <b>5</b>                 |              |                             |
| Rims summer:                       | <b>Aluminium</b>         |              |                             |
| Category:                          | <b>Passenger Car</b>     |              |                             |
| Oil level:                         | <b>OK</b>                |              |                             |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                             |

**Options**

|                                |                              |                      |                          |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD                       |                              | Central consol F     |                          |
| GPS storage                    | <b>SD</b>                    | Luggage cover        |                          |
| GPS storage                    |                              | Rear parking sensors |                          |
| Windows electric F             |                              | Type of Tow bar      | <b>Tow bar removable</b> |
| Windows electric R             |                              |                      |                          |
| Cruise Control                 |                              |                      |                          |
| Steering wheel multifunctional |                              |                      |                          |
| Radio multimedia               |                              |                      |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                          |
| Type of Lining                 | <b>Lining semi-leather</b>   |                      |                          |
| Type of climate control        | <b>Autom climate control</b> |                      |                          |

**Limited Technical Inspection**

|                     |               |                     |               |
|---------------------|---------------|---------------------|---------------|
| Airco functioning   | <b>OK</b>     | Battery functioning | <b>Yes</b>    |
| Tires wear profile  | <b>OK</b>     | Power steering      | <b>Yes</b>    |
| Idle position       | <b>OK</b>     | Sound engine        | <b>NOT OK</b> |
| Engine startingtime | <b>NOT OK</b> | Clutch test         | <b>NOT OK</b> |
| Exhaust gass        | <b>OK</b>     | Wiper fluid level   | <b>OK</b>     |
| Handbrake           | <b>OK</b>     | Transmission        | <b>NOT OK</b> |
|                     |               | Lighting            | <b>OK</b>     |
|                     |               | Wiperblades         | <b>OK</b>     |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Bridgestone: 4 mm</b> | Fr.R. | <b>Bridgestone: 4 mm</b> |
|               | Re.L.                            | <b>Semperit: 7 mm</b>    | Re.R. | <b>Semperit: 7 mm</b>    |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|   |                |
|---|----------------|
| <b>Total cost ex VAT</b>  | <b>2052,00</b> |
| <b>Alloy rim R L, Scratch(es), LI - Repair and paint (complete)</b> | <b>95,00</b>   |



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door panel F L, Broken, E - Replace

114,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80





Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



Engine, Not functioning (well), Acceptable 0,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Floor covering F L, Burned, Smart repair 64,32



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Engine protective plate, Deformed / Strained, Acceptable 0,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

