



**BMW 2 ACTIVE TOURER: 1KSJ228**

|                                    |                                  |              |                               |
|------------------------------------|----------------------------------|--------------|-------------------------------|
| Vinnumber:                         | <b>WBA2B31010V542078</b>         | Versionname: | <b>1.5 216D ACTIVE TOURER</b> |
| First Registrationdate:            | <b>23/06/2015</b>                | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>50447</b>                     | Power Kw:    | <b>85</b>                     |
| Bodytype:                          |                                  | Body color:  | <b>Black</b>                  |
| Gearbox:                           | <b>MAN 6 VIT</b>                 | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Front</b>                     | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Diesel</b>                    | Oil level:   | <b>OK</b>                     |
| Maintenance:                       | <b>SERVICE IN 17000KM 7 2020</b> | Parking lot: | <b>3527</b>                   |
| Maintenance:                       | <b>OK</b>                        |              |                               |
| Battery functioning:               | <b>Yes</b>                       |              |                               |
| Number of doors:                   | <b>5</b>                         |              |                               |
| Number of seats:                   | <b>5</b>                         |              |                               |
| Number head rests:                 | <b>5</b>                         |              |                               |
| Rims summer:                       | <b>Aluminium</b>                 |              |                               |
| Category:                          | <b>Passenger Car</b>             |              |                               |
| Oil level:                         | <b>OK</b>                        |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>                       |              |                               |

**Options**

|                                |                              |                      |
|--------------------------------|------------------------------|----------------------|
| GPS storage                    |                              | Central consol F     |
| GPS storage                    | <b>HD</b>                    | Luggage cover        |
| Windows electric F             |                              | Rear parking sensors |
| Windows electric R             |                              |                      |
| Cruise Control                 |                              |                      |
| Steering wheel multifunctional |                              |                      |
| Radio multimedia               |                              |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>205/60/16/92 V LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>BF Goodrich: 5 mm</b> | Fr.R. | <b>BF Goodrich: 5 mm</b> |
|                                  | Re.L. | <b>Hankook: 6 mm</b>     | Re.R. | <b>Hankook: 6 mm</b>     |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |                |
|-------------------|----------------|
| Total cost ex VAT | <b>1273,66</b> |
|-------------------|----------------|

|   |               |
|---|---------------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | <b>211,80</b> |
|---|---------------|



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Tailgate, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



