



BMW 2 ACTIVE TOURER: 1LLJ306

Vinnumber:	WBA2B11020V295545	Versionname:	1.5 214D ACTIVE TOURER
First Registrationdate:	20/10/2015	Fiscalpower:	
Expertise Mileage:	78477	Power Kw:	70
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Total cost ex VAT	1634,30
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00






Roof pillar L, Chemical polution, LI - Repair and paint (complete)

220,18



Roof, Chemical polution, LI - Repair and paint (complete)

481,50




Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), LI - Repair and paint (complete)

0,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

0,00



Wing F L, Chemical polution, LI - Repair and paint (complete)

220,18



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Sill outer L, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display