



MERCEDES CLA: 1SCB684

Vinnumber:	WDD1173121N507658	Versionname:	CLA 180 d AMG Line
First Registrationdate:	5/04/2017	Fiscalpower:	
Expertise Mileage:	74389	Power Kw:	80
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4306
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-Alcantara		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

225/40/18/92 Y LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1235,04
Roof pillar R, Dent(s), LI - Repair and paint (complete)	220,18



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Floor covering F R, Stain, Acceptable

0,00

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)


211,80





Roof, Chemical polution, LI - Repair and paint (complete)

529,50



Tailgate, Scratch(es), 67 - Polish

0,00

No pictures to display

Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Dent(s), PDR - Paintless dent repair

63,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display