



OPEL Insignia: 1HGV228

Vinnumber:	WOLGM8ER9E1130500	Versionname:	INSIGNIA BRE ecoFL.Business 120PK
First Registrationdate:	17/07/2014	Fiscalpower:	
Expertise Mileage:	157111	Power Kw:	88
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3309
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/101 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 2402,63

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R, Rust, Acceptable

0,00



Rear window, Scratch(es), Acceptable

0,00



Seat cover R R, Stain, Cleaning

25,00



Alloy rim F L, Rust, Acceptable

0,00



Windscreen, Repaired, Acceptable

0,00

No pictures to display

Alloy rim R L, Rust, Acceptable

0,00



Wing R R, Scratch(es), 67 - Polish

0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Alloy rim R R, Rust, Acceptable

0,00



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper R, Deformed / Strained, Le - Replace and paint

651,00



