


**BMW SERIE 3 GRAN TURISMO: 1JVB747**

Vinnumber:	<b>WBA3Y11000GD87456</b>	Versionname:	<b>318D</b>
First Registrationdate:	<b>4/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>76746</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2616</b>
Maintenance:	<b>IN 8000 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/97 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------








Total cost ex VAT	<b>1110,63</b>
-------------------	----------------

Roof, Dent(s) and scratch(es), Acceptable	<b>0,00</b>
---	-------------

*No pictures to display*

Boot carpet, Stain, Acceptable	<b>0,00</b>
--------------------------------	-------------

*No pictures to display*

Door R R, Dent(s), PDR - Paintless dent repair	63,00
	
Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	307,80
	
Wing R R, Dent(s), Acceptable	0,00
No pictures to display	
Seat cover F L, Worn, P - Check	0,00
	
Backrest cover R R, Stain, Acceptable	0,00
No pictures to display	
Bonnet, Dent(s), PDR - Paintless dent repair	63,00
	
Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Alloy rim R L, Scratch(es), Acceptable	0,00
No pictures to display	
Interior, Not original part, E - Replace	99,71
	
Door F L, Dent(s) and scratch(es), It - Spot repair	115,56
	
Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	

Sill trim R, Scratch(es), It - Spot repair

115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Air vent R M, Broken, E - Replace

156,00



Floor covering F L, Stain, Acceptable

0,00

No pictures to display