



SKODA Fabia: 1HHA108

Vinnumber:	TMBJK25J2F3020981	Versionname:	FABIA COMBI Ambition DPF 75PK
First Registrationdate:	18/07/2014	Fiscalpower:	
Expertise Mileage:	142667	Power Kw:	55
Bodytype:	Break	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2811
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 T Steel			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2129,86
Bumper R, Deformed / Strained, Le - Replace and paint	535,20





Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Armrest F Mid, Damaged, Smart repair 64,32



Compressor, Missing, E - Replace 0,00



Roof, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 241,34



Trunk lid covering R, Scratch(es), Smart repair 110,64



Wheel cover F R, Scratch(es), E - Replace 24,00





Door trim F R, Deformed / Strained, Acceptable 0,00



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Wheel cover F L, Scratch(es), E - Replace 24,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Headlight L, Scratch(es), E - Replace 336,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display