



VOLVO XC60: 1KFT914

Vinnumber:	YV1DZ73CDF2760101	Versionname:	2.0 D4 2WD 133KW GEARTRONIC SUMMUM
First Registrationdate:	23/04/2015	Fiscalpower:	
Expertise Mileage:	118677	Power Kw:	133
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 17910 KM	Parking lot:	3401
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/60/18/107 V LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1443,82
Alloy rim F R, Scratch(es), Acceptable	0,00

Door F L, Bad repair, Paint 0,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Internal Boot Lining L, Stain, Cleaning 25,00



Door panel F R, Hole, Smart repair 110,64



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bad repair, Forfeit 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bad repair, Paint 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Windscreen, Stone chip(s), Windscreen repair 0,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 417,84

